

### **RU-C2 Remedial Action**



# RU-C2 Pre-Characterization PARCEL C

Hunters Point Shipyard March 2012



Contract No. N62473-06-D-2206 Delivery Order No. 0093






#### **Building 258 VOC Remediation Area**

 DP1 through DP4 encountered competent bedrock (serpentine) at 3 feet bgs

#### Options

- Air rotary rig required to penetrate bedrock
  - · Access limited by open trenches
- Soil vapor monitoring points

**Building 258 VOC Remediation Area** 








# Building 258 VOC Investigation Options

- Proposed Soil Vapor Sampling
  - 8 Locations at 3 feet bgs
- SV-16 and SV-17: Target upgradient portion of remediation area.
- SV-18, SV-19: Target areas nearest to Building 258 and potential release areas.
- SV-21, SV-22: Target locations proposed nearest to existing monitoring well IR28MW188F.
- SV-20, SV-23: Target downgradient portions of the remediation area outlined in the ROD. Locations are nearest to open utility excavation pits.

#### **Building 258 VOC Remediation Area**








# Building 258 VOC Investigation Options

- Scenario-1
  - Results: All detections below SGALs.
  - Data to RD contractor for no action, MNA, or ARIC.
- Scenario-2
  - Results: Select locations slightly above SGALs.
  - Data to RD contractor for possible localized hydropunch investigation with drill rig in areas with the highest detections in soil vapor.
  - MNA, localized bio injections, or ARIC.

#### **Building 258 VOC Remediation Area**







#### Scenario-3

Results: Select locations significantly above SGALs

- Data to RD contractor for possible hydropunch investigation.
- Localized bioremediation injections in areas with the highest detections in soil vapor.
- Larger scale bioremediation across entire area, MNA, or ARIC.